

Toughpower™

P/N: ADP95W0003

Ultra Slim 95W

Universal Laptop AC Power Adapter

Setup Guide



1

check you laptop adapter output voltage & current

It showed the output voltage is DC 19, output current is 3.42A, ADP95W0003 output only 19V



Original DC tip

2


choice your NB Tip

Choose a tip which is the same as the original DC tip.



3

Take the tip from the tip set.



4

Connect the tip to Terminal B
(fool-proof built in)



5

Terminal B connected



6

Connect AC Power Cord to the adapter



7

AC power connected




8

Connect the tip with your laptop.



9

If your laptop is not plugged into the electrical outlet, the power source will be your battery.





10

If your laptop connects to the electrical outlet, the power source will be the AC power, and then installation is complete.



11

Charge USB device by 95W adapter

When applying the USB charger, please connect the power charge cable of your electrical device to the USB port of your adapter.

You can charge any electrical device such as mobile phone, MP3, USB mobile power bank, PDA, etc.

Please make sure your electrical device consumes 5V input, some devices may need additional power charging connectors.